ECS Configuration Change Request

CCR No. 96-0461	**Logged Date** 5/02/96	**Rev.**	**Request Type** CCR

Priority Routine ☐ Urgent ☐ Emergency ☒	**Affected Release** Rel B	**Change Class** II

Title (description) Redeployment of EP6 Hardware and Software

Documents Affected	**Source Nos** (RID, NCR, etc.) **or Tech Reference** CCR No.

RTM Change ☐   **Start New Baseline** ☒

Problem

EP6 has completed its mission and was officially shut down as of 4/26/96. The hardware and software will be redeployed to support other efforts as soon as possible. There are currently 3 processors available for reassignment: epserver (HP735), epdatasrv (Sun Sparc 20) and, epfbb (HP 715).

Proposed Solution

1. The edfbb DCE Servers (CDS, DFS, Sec) 1.03 licenses will be reassigned to sparrow in the EP& I&T/Production cell.
2. epdatasrv will be redeployed to the EP7 I&T/Production cell.
3. The simms on epdatasrv will be redeployed to the view server in Release A.
4. epserver and edfbb are as yet uncommitted.
5. Other componenets of EP6 will be redeployed as needed.

Impact Analysis:

Organizations Affected: BOO ☐   Contracts ☐   ESO ☐   FOS ☐   M&O ☐

QA ☐   Rel. A ☐   Rel. B ☒   Rel. IR1 ☐   MRS ☐   SMO ☐   Subconts ☐

Other _____

Cost:	None ☒	Small ☐ (Not exceeding $100,000)	Medium ☐ ($100,000 to $500,000)	Large ☐ (Over $500,000)

Schedule: None ☒   Other   Immediate

Additional LOC _____   Man-Months _____

Materials

Originator   Paula Linville _____   _____
                              Signature   Date

Office	MRS	Office Manager		
			Signature	Date

Disposition   Approved ☐   Approved w/Comment ☒   Forward ☐   Disapproved ☐

Comments:
Paula L. - Task Leader

CCB Chairperson _____